


## Transmission Chart – FS03-PLR



W (nm)	T (%)	W (nm)	T (%)	W (nm)	T (%)	W (nm)	T (%)	W (nm)	T (%)
750.00	33.95	670.00	32.50	590.00	30.24	510.00	34.05	430.00	33.32
745.00	33.45	665.00	32.46	585.00	30.20	505.00	33.71	425.00	32.72
740.00	33.08	660.00	32.35	580.00	30.61	500.00	33.35	420.00	31.92
735.00	32.90	655.00	32.28	575.00	32.12	495.00	32.99	415.00	30.71
730.00	32.73	650.00	32.24	570.00	35.10	490.00	32.74	410.00	28.83
725.00	32.59	645.00	32.19	565.00	37.78	485.00	32.76	405.00	25.78
720.00	32.60	640.00	32.09	560.00	36.80	480.00	33.52	400.00	21.05
715.00	32.54	635.00	32.00	555.00	36.04	475.00	35.14	395.00	14.70
710.00	32.54	630.00	31.82	550.00	35.74	470.00	36.99	390.00	7.83
705.00	32.59	625.00	31.70	545.00	35.59	465.00	37.67	385.00	3.01
700.00	32.54	620.00	31.55	540.00	35.43	460.00	36.40	380.00	0.87
695.00	32.51	615.00	31.37	535.00	35.19	455.00	35.70		
690.00	32.57	610.00	31.21	530.00	35.01	450.00	35.20		
685.00	32.55	605.00	30.98	525.00	34.83	445.00	34.71		
680.00	32.51	600.00	30.71	520.00	34.60	440.00	34.27		
675.00	32.48	595.00	30.44	515.00	34.36	435.00	33.81		